944-SPEC - 944SPEC - low cost wheel to wheel racing

Generated: 4 September, 2025, 10:56

۱۸/	hat	ic	th	ic2	
vv	nat	1S	тn	IIS Z	

Posted by BritRacer - 25 May 2015 07:50

Anyone know what this is and whether it is required? It seems to be connected at one end to the clutch housing and the other end was just clamped to the top of the intake manifold. I did some research and

the only image I found similar was from a 928 flywheel sensor.

Re: What is this?
Posted by joeblow - 26 May 2015 09:12

Dealer reference sensor for diagnostics only. No you do not need it.